



# Inspection Report

Inspection Date: 2024/10/19

## Wheel Loader

### General Information

Maker	HITACHI
Model Number	LX20-7
Year	
Hour (h)	3361
Serial Number	HFK4E100E00006213

### Note for External Appearance

- Repainted
- The body is rusty and has scratches



### Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

### Note for Upper Structure



### Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

### Note for Operating Component



### Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

### Note for Undercarriage



### Documents

Automobile Inspection Certificate	No
-----------------------------------	----

### Note for Engine



Admin. No. 3000065125

\*This report is only for your reference. We are not responsible for the actual condition of checked item.