



Inspection Report

Inspection Date: 2026/07/24

Excavators

General Information

#ERROR!	HITACHI		
Model Number	ZX17U-5A		
Year	2022		
Hour (h)	991	Meter	Working
Serial Number	HCMABAA0H00026968		

Options

- CNP	- Speed changer
- Multilever	
- Blade	- Pippings

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		400		

Note for External Appearance

- Repainted
- The arm is reinforced



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000087958

*This report is only for your reference. We are not responsible for the actual condition of checked item.