



# Inspection Report

Inspection Date: 2025/12/11

## Wheel Loader

### General Information

Maker	KOMATSU
Model Number	WA40-8
Year	2016
Hour (h)	2382
Serial Number	KMTWA133CGE070477

### Note for External Appearance

- Repainted
- The body is rusty and has some scratches



### Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

### Note for Upper Structure



### Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

### Note for Operating Component



### Engine

Model	4D88E-7PAA
Serial Number	14800
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

### Note for Undercarriage



### Documents

Automobile Inspection Certificate	No
-----------------------------------	----

### Note for Engine

- There is a gas smell during operation



Admin. No. 3000079557

\*This report is only for your reference. We are not responsible for the actual condition of checked item.