

General Information		
Maker	CAT	
Model Number	304ECR	
Year	2012	
Hour (h)	1307 Meter	Working
Serial Number	CAT0304FHTSR00105	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	1 lay
Boom	Left	Oil oozing	Scratch	No
	Right	N/A	N/A	140
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		590		

Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	350	350
Idler	ОК	OK
Sprocket	ОК	OK
Pin Bush	ОК	OK
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

Engine	
Model	C2 4
Serial Number	7CV6514
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Inspection Date: 2020/09/06

Note for External Appearance

- The VIN stamp on the body is unclear because the body is rusty and decayed - The right side cover won't open
- smoothly



Note for Upper Structure

- The boom cylinders are decayed; there are plating peeling
- The blade has some dents



Note for Undercarriage



Note for Operating Component

- The stay of the seat is severely decayed
- Inside of the canopy is severely decayed
- ROPS (Rollover Protection Structure)



Note for Engine

- The fan belts makes squeaky sounds when the engine starts



Admin No.

3000015558