



Inspection Report

Inspection Date: 2024/12/14

Excavators

General Information

| | | | |
|----------------------|-----------|--------------|---------|
| Maker | KOMATSU | | |
| Model Number | PC78US-10 | | |
| Year | 2019 | | |
| Hour (h) | 2526 | Meter | Working |
| Serial Number | 36826 | | |

Options

| | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | - Piping |
| - Arm Crane | |
| - EPA | |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|----------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | No | No | |
| Arm | | No | No | Small |
| Bucket | | No | No | Small |
| Bucket Size (mm) | 650 | | | |

Note for External Appearance

- Partially repainted



Undercarriage


| | | |
|---------------------|------------------------------|--------------|
| Shoe Type | Steel shoes with rubber pads | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 450 | 450 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

Note for Upper Structure



Note for Undercarriage

- The rubber pads are deteriorated, cracked and chipped
- The shoes have some kinks




Engine

| | |
|-------------------------|---------------|
| Model | SAA4D95LE-6-C |
| Serial Number | 730773 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | Unchecked |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for Operating Component

- The upper part of the cabin has some small dents



Note for Engine



Admin No. 3000067402