

308E CR Hydraulic Shovel

BASIC INFORMATION

Inspection Date		Model	308E CR	Serial No.	HAM00434
Date of Manufacture		Hourmeter	2631 HR	Condition of Hourmeter	
Hourmeter (Estimated)		Engine No.		Job Status	Rental
Accident History		Cabin/Canopy	Cabin	Cabin Type	Standard
Front Attachment	Standard	Super long length(m)		Type of Shoe	Grouser with Pad
Width of Track Shoe	450	Bucket/Attachment	Standard BK	Stamp	
Others	Air Conditioner, ML Crane, Multi Lever, Blade				

OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Swing	Normal
Wear: Swing Bearing	Slight	Traveling	Normal	Front Attachment	Normal
Pump Device	Normal				

UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	No	Wear: Track Link Extension (Right)	Excessive	Wear: Track Link Extension (Left)	Excessive
Wear: Track Link Tread(Right)	Slight	Wear: Track Link Tread(Left)	Slight	Wear: Track Link Pins (Right)	Slight
Wear: Track Link Pins (Left)	Slight	Wear: Track Shoe/Rubber Shoe	Slight	Bent/Broken/Missing: Track Shoe	No
Wear: Rubber Pad	Moderate/Within Service Limit	Broken/Missing: Rubber Pad	No	Missing: Rubber Pad	More than 10 Piece
Broken/Crack: Rubber Shoe(Right)		Broken/Crack: Rubber Shoe(Left)		Missing: Rubber Shoe Core	
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight	Oil Leak: Rollers	1~4 Pieces 下ローラ右: 1#漏れ
Broken/Missing: Rollers	None	Wear: Front Idler(Right)	Slight	Wear: Front Idler(Left)	Slight
Wear: Sprocket(Right)	Slight	Wear: Sprocket(Left)	Slight	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

FRONT & PINS

Boom	Normal	Arm	Reinforcement	Wear: Boom Foot Pin	Slight
Wear: Boom/Arm Joint Pin	Slight	Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear/Deformation: Bucket	Good	Wear/Deformation: Blade	Wear: Moderate/Within Service Limit		

OIL/WATER/AIR LEAK

Oil Leak: Front Pipes	No	Oil Leak: Boom Cylinder(Right)	No	Oil Leak: Boom Cylinder(Left)	
Oil Leak: Arm Cylinder(Right)	No	Oil Leak: Arm Cylinder(Left)		Oil Leak: Bucket Cylinder(Right)	No
Oil Leak: Bucket Cylinder(Left)		Oil Leak: Offset Cylinder		Oil Leak: Blade Cylinder	No
Oil Leak: Engine	No	Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No
Oil Leak: Pilot Valve	No	Oil Leak: Center Joint	No	Oil Leak: Swing Device	No
Oil Leak: Pump Device	No				

APPEARANCE

Engine Cover	Good Condition	Side Covers	Deformed/Dent	Under Covers	Deformed/Dent
Counter Weight	Scratched	Main frame	Good Condition	D Frame	Deformed/Dent
Track Frame	Good Condition	Cabin	Deformed/Dent	Door	Good Condition

INTERIOR

Cabin Interior	Good Condition	Seat	Good Condition	Console	Good Condition
Air conditioner	Good Condition	Freon gas inspection			

OVERALL RATING

Appearance Evaluation	Fair	Rust/Corrosion	Slight	Overall Rating	Good
Special Notes	<ul style="list-style-type: none"> ・下ローラ右: 1#漏れ ・キャブミラー損傷 				