



Inspection Report

Inspection Date: 2018/09/29

Generator

General Information

Maker	DENYO
Model Number	DCA-220ESM
Year	
Hour (h)	3795
Serial Number	3741571

Engine

Model	6D24-TLE2B
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for External Appearance

The paint has deteriorated over time

Note for Control Panel

The green "SELECT" switch on the operator panel is broken

Note for Engine

Admin. No. 2018090354

*This report is only for your reference. We are not responsible for the actual condition of checked item.