



Inspection Report


Inspection Date: 2017/09/15

Excavators


General Information			
Maker	KOMATSU		
Model Number	PC58UU-3EO		
Year	2004		
Hour (h)	3616	Meter	Working
Serial Number	22401		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		600		


Note for External Appearance
Repainted



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
- Traveling motion unchecked
- The rubber shoes have deteriorated over time


Engine	
Model	4D88E-5XBB
Serial Number	2760
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn


Note for Engine
Fuel leak from around the fuel filter


Admin No. 2017090425