

Inspection Report

Inspection Date: 2023/10/07

Excavators

General Information		
Maker	KOMATSU	
Model Number	PC78US-10	
Year	2015	
Hour (h)	720 Meter	Working
Serial Number	KMTPC258LEA030025	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
Boom	Right	N/A	N/A	Sillali
	Arm	No	No	Small
	Bucket	No	No	Small
Bucket Siz	ze (mm)	645		

Undercarriage

ondoroannago		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

Engine	
Model	SAA4D95LE-6-C
Serial Number	706708
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Options - CAB - Speed changer - Air conditioner - Blade - Arm Crane - EPA

Note for External Appearance



Note for Upper Structure	

Note for Undercarriage	

Note for Operating Component	
Note for Engine	



Admin No.

*This report is only for your reference. We are not responsible for the actual condition of checked item.