



Inspection Report

Inspection Date: 2018/09/21


Excavators

General Information			
Maker	KOMATSU		
Model Number	PC78UU-6EO		
Year	2004		
Hour (h)	4556	Meter	Working
Serial Number	24175		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	No	No	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)		640		

Note for External Appearance
The body is partly repainted




Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	460	460	
Idler	OK	NG	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage
One of the shoes is slightly loose




Engine	
Model	S4D95LE-3
Serial Number	102924
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine
The engine won't start even with starter cables (the starter motor is broken)



Admin No. 2018090273