



Inspection Report

Inspection Date:

Forklift

General Information

Maker	KOMATSU
Model Number	FD25T-17
Year	2015
Hour (h)	4041
Serial Number	M228-341517

Note for External Appearance

- The steering sometimes becomes heavy, and the machine sometimes cannot turn right
- Maximum lift: 3,000mm
- Vehicle weight: 4,070kg
- Side shift
- Tire size: Front 5.50-15 8PR, Rear 6.00-9 10PR
- Oil oozing from the left lift cylinder

Engine

Model	4D94LE
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- The meter was replaced (+ 23,200h according to the seller)

Note for Engine

Other Information

Admin. No. 3000088896

*This report is only for your reference. We are not responsible for the actual condition of checked item.