



Inspection Report

Inspection Date: 2026/07/03

Excavators

General Information

#ERROR!	KOMATSU		
Model Number	PC38UU-5		
Year	2014		
Hour (h)	3705	Meter	Working
Serial Number	KMTPC220E04016196		

Options

- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		620		

Note for External Appearance

- Repainted
- The covers have dents and scratches
- The right cover is missing



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The crane monitor is difficult to read



Note for Engine



Admin No. 3000087820

*This report is only for your reference. We are not responsible for the actual condition of checked item.