



Inspection Report

Inspection Date: 2022/08/20

Wheel Loader

General Information

Maker	HITACHI
Model Number	ZW40
Year	2008
Hour (h)	2916
Serial Number	S67-00381

Note for External Appearance

- The body is damaged



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component

- The seat has been repaired



Engine

Model	V2403
Serial Number	8U0089
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 3000042463

*This report is only for your reference. We are not responsible for the actual condition of checked item.