



# Inspection Report

Inspection Date: 2022/06/17

## Roller

### General Information

<b>Maker</b>	SAKAI
<b>Model Number</b>	TS200
<b>Year</b>	1997
<b>Hour (h)</b>	3179
<b>Serial Number</b>	TTS6-23007

### Engine


<b>Model</b>	A-6BG1QJ-01
<b>Serial Number</b>	G1-526045
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for External Appearance

- The canopy is cracked



### Note for Undercarriage



### Note for Operating Component

- The seat is torn  
- The transmission does not work smoothly



### Note for Engine



Admin. No. 3000040720

\*This report is only for your reference. We are not responsible for the actual condition of checked item.