



Inspection Report

Inspection Date: 6/28/2016

Excavator

General Information

Maker	KOBELCO
Model Number	SK60SR
Year	2001
Hour (h)	4846
Serial Number	YT0 [REDACTED]

Note for External Appearance

- No caution plate
- Repainted



Upper Structure

Boom Cylinder (Left)	No oil leak
Boom Cylinder (Right)	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	なし
Swing	No backlash and play

Note for Upper Structure

- 4 sides reinforced (arm)
- The boom does not have enough power



Undercarriage

Swivel Joint	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage

- Steel shoes + rubber pads
- Some pads are lost



Note for Operating Component

- Sheet repaired



Engine

Model	CC-4JG1
Serial Number	210031
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Engine

Oil oozing from the engine head

