



# Inspection Report

Inspection Date: 2022/04/11

## Roller

### General Information

<b>Maker</b>	SAKAI
<b>Model Number</b>	SW352-1
<b>Year</b>	2011
<b>Hour (h)</b>	111
<b>Serial Number</b>	1SW-20220

### Engine

<b>Model</b>	D1503
<b>Serial Number</b>	AS0060
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for External Appearance

- Owner designated color



### Note for Undercarriage



### Note for Operating Component



### Note for Engine

- Vibrating operation has been checked, to be in normal condition.



Admin. No. 3000040081

\*This report is only for your reference. We are not responsible for the actual condition of checked item.