



# Inspection Report

Inspection Date: 2018/05/29


## Excavators

General Information			
Maker	SUMITOMO		
Model Number	SH75X-3		
Year			
Hour (h)	6997	Meter	Working
Serial Number	5569		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	Yes	Small
Bucket Size (mm)		720		

Note for External Appearance
<ul style="list-style-type: none"> <li>- The right and left front covers are partly deformed</li> <li>- No rear-view mirror</li> <li>- The boom does not have its working lights</li> <li>- A working light on the cabin is lost</li> <li>- The radio antenna is broken</li> </ul>




Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
There are some dents on the bucket sides




Note for Undercarriage




Engine	
Model	4TNE96-SH
Serial Number	30963
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
<ul style="list-style-type: none"> <li>- The seat is partly torn</li> <li>- The covers in the cabin are partly cracked</li> <li>- The ashtray is damaged</li> </ul>



Note for Engine
<ul style="list-style-type: none"> <li>- Oil oozing from the tappet cover</li> <li>- Oil oozing from around the engine oil element</li> </ul>



Admin No. 2018050706