

Inspection Report

Inspection Date: 2017/08/08

Excavators

General Information		
Maker	KUBOTA	
Model Number	RX-403S	
Year	2005	
Hour (h)	4009 Meter	Working
Serial Number	60148	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	Flay
Boom	Left	No	No	Small
Doom	Right	N/A	N/A	Sman
	Arm	No	No	Big
	Bucket	No	No	Big
Bucket Siz	ze (mm)) 550		

Undercarriage

Undercarriage		
Shoe Type	Rubber	
Swing Circle	Unchecked	
	Left	Right
Shoe Width (mm)	300	300
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

ModelD1Serial Number50Engine Oil LeakNoEngine Oil GaugeOrRadiatorOrExhaust ColorNoBlow-byNoEngine SoundOrHydraulic PumpNo	0093 o oil leak C
Engine Oil Leak No Engine Oil Gauge Or Radiator Or Exhaust Color No Blow-by No Engine Sound Or	oil leak <
Engine Oil Gauge Or Radiator Or Exhaust Color No Blow-by No Engine Sound Or	(
Radiator Of Exhaust Color No Blow-by No Engine Sound Of	ζ
Exhaust Color No Blow-by No Engine Sound Of	-
Blow-by No Engine Sound Of	ormal
Engine Sound Of	
Hydraulic Pump No	
2 .	oil leak
Water Pump No	water leak
Oil Cooler No	oil leak
Motor Un	checked
Multi Lever No	

Options - CNP - Speed changer - Multilever - Blade

Note for External Appearance

Repainted



Note for Upper Structure	

Note for Undercarriage	



Note for Engine



Admin No.

2017080145

*This report is only for your reference. We are not responsible for the actual condition of checked item.