



# Inspection Report

Inspection Date: 2021/11/26

## Roller

### General Information

<b>Maker</b>	SUMITOMO
<b>Model Number</b>	HW41VW-5
<b>Year</b>	2006
<b>Hour (h)</b>	1731
<b>Serial Number</b>	WO4A5-0182

### Engine

<b>Model</b>	
<b>Serial Number</b>	120254D6
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for External Appearance

- The body is rusty and damaged



### Note for Undercarriage



### Note for Operating Component

- The seat is partly torn



### Note for Engine



Admin. No. 3000036349

\*This report is only for your reference. We are not responsible for the actual condition of checked item.