



Inspection Report

Inspection Date: 2024/07/03

Excavators

General Information

Maker	KOMATSU		
Model Number	PC200LC-8N1		
Year	2007		
Hour (h)	13463	Meter	Working
Serial Number	KMTPC197P02311151		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	Oil leak	No	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		835		

Note for External Appearance

- 15m super long front




Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	700	700
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	NG	OK
Shoe Link	OK	OK


Note for Upper Structure

- The back of the boom has been welded (please check the photos)



Note for Undercarriage

- One left lower roller is broken




Engine

Model	SAA6D107E-1
Serial Number	6D107-26511362
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn
- With rear-view camera



Note for Engine



Admin No. 3000059565