



Inspection Report

Inspection Date: 2021/08/13

Excavators

General Information

Maker	HITACHI		
Model Number	ZX20U		
Year	2014		
Hour (h)	1815	Meter	Working
Serial Number	HCM1MY00C00010980		

Options


- CNP	- Speed changer
- Multilever	
- Blade	- Pippings

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)	390			

Note for External Appearance

- The right side of the body is deformed




Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- 4 sides of the arm have been reinforced



Note for Undercarriage

- The rubber shoes are worn



Engine

Model	S773L
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000034234