



Inspection Report

Inspection Date: 2025/04/04

Excavators

General Information

Maker	KUBOTA		
Model Number	U-40-6E		
Year	2018		
Hour (h)	3102	Meter	Working
Serial Number	30839		

Options


- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	Yes	Small
Bucket Size (mm)	550			

Note for External Appearance

- The body has some scratches and rust




Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	350	350	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- The bucket cylinder has some cracks (please check the photo).



Note for Undercarriage



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000072498