



Inspection Report

Inspection Date: 2018/08/09

Dozer

General Information

Maker	KOMATSU
Model Number	D65PX-15EO
Year	2009
Hour (h)	5638
Serial Number	71671

Note for External Appearance

ROPS Cabin



Upper Structure

Blade Tilt Cylinder	No oil leak	
	Left	Right
Lift Arm Cylinder	No oil leak	No oil leak
Blade Angle Cylinder	No oil leak	No oil leak
Travel Motor	No oil leak	No oil leak

Note for Upper Structure



Undercarriage

	Left	Right
Shoe Width (mm)	950	950
Idler	OK	OK
Shoe Link	NG	NG
Sprocket	OK	OK
Track Roller	NG	NG
Upper Roller	OK	OK
Pin Bush	NG	NG

Note for Operating Component



Note for Undercarriage

The pin bushes of the shoe links are severely worn and partly cracked



Engine

Model	SAA6D114E-3-A
Serial Number	-
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Engine



Admin. No. 2018080008

*This report is only for your reference. We are not responsible for the actual condition of checked item.