



Inspection Report


Inspection Date: 2018/08/08

Excavators


General Information			
Maker	KOMATSU		
Model Number	PC78US-6NO		
Year	2006		
Hour (h)	4715	Meter	Working
Serial Number	9413		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Pipings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		645		


Note for External Appearance


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
4 sides of the arm have been reinforced


Note for Undercarriage
- Some of the track bolts are cut - The rubber pads are partly worn


Engine	
Model	S4D95LE-3-A
Serial Number	112877
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The slide door won't close because some parts are broken


Note for Engine


Admin No. 2018070640