

Inspection Report

Inspection Date: 2024/08/02

Excavators

General Information		
Maker	HITACHI	
Model Number	ZX120-3	
Year	2011	
Hour (h)	5758 Meter	Working
Serial Number	HCM1R100L00087118	

Upper Structure

		Cylinder		Play	
		Oil Leak	Scratch/Rust	Flay	
Boom	Left	No	No	Big	
	Right	No	No	ыg	
	Arm	No	No	Big	
	Bucket	No	No	Big	
Bucket Siz	ze (mm)	885			

Undercarriage

onderournage		
Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

Engine	
Model	AJ-4JJ1XYSA-03
Serial Number	135253
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Options - CAB - Speed changer - Multilever - Air conditioner - Arm Crane - Air conditioner

Note for External Appearance



Note for Upper Structure	

Note for Undercarriage	•





Admin No.

3000061141

*This report is only for your reference. We are not responsible for the actual condition of checked item.