



Inspection Report

Inspection Date: 2023/09/07

Excavators

General Information

Maker	KOBELCO		
Model Number	SK70SR		
Year	2006		
Hour (h)	8309	Meter	Working
Serial Number	YT04-08182		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
	- Breaker Pippings
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	No
	Right	N/A	N/A	
Arm		Oil oozing	No	No
Bucket		Oil leak	Yes	Small
Bucket Size (mm)	680			

Note for External Appearance

- The body has rust and dents



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- No bucket side cutters



Note for Undercarriage

- Oil oozing from the reduction drives of the travel motors
- Many rubber pads are missing



Engine

Model	CC-4JG1
Serial Number	290751
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Not enough cooling water
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine

- Oil oozing from the whole engine



Admin No. 3000050381