



Inspection Report


Inspection Date: 2018/02/21

Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-505		
Year	2007		
Hour (h)	4291	Meter	Working
Serial Number	70168		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		610		


Note for External Appearance


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The blade is partly worn and has some dents


Note for Undercarriage
- Oil oozing from 2 of the right lower rollers and 1 of the left lower rollers
- The rubber pads are partly worn and chipped
- Oil oozing from the bottom of the body


Engine	
Model	V2203
Serial Number	7S2712
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	No oil leak

Note for Operating Component
The seat has been fixed


Note for Engine


Admin No. 2018020325